

AUSTRALIAN FOOD & FIBRE POLLUTION INCIDENT RESPONSE MANAGEMENT PLAN

WARREN COTTON GIN

LICENCE NO. 11123

REVIEWED AND APPROVED: 20/10/2024

Pollution incident response management plan

Licence number: 11123

Approved by: Wayne Towns Date: 20/10/2024

Position/Title: General Manager Ginning

Purpose:

AFF Properties No 1 Pty Ltd (AFF) holds an Environment Protection Licence with the NSW Environment Protection Authority (EPA) for Narrabri Gin. As per the *Protection of the Environment Operations Act 1997* (the POEO Act), the holder of an Environment Protection Licence must prepare, keep, test and implement a pollution incident response management plan (PIRMP) that complies with Part 5.7A of the POEO Act in relation to the activity to which the licence relates.

The PIRMP ensures the comprehensive and timely communication about a pollution incident to staff at the premises, the relevant authorities, and people outside the facility who may be affected. It helps to minimise and control the risk of a pollution incident at the facility and ensures that, if a pollution incident were to occur, staff at the facility understand the risks, controls and their respective responsibilities. In summary, this document aims to:

- Set out the requirements for the notification, response, and management of potential pollution incidents.
- Nominate key staff responsible for the notification, response, and management of incidents, including a description of their responsibilities.
- Minimise and control the risk of a pollution incident at the facility through the identification of hazards and risks and the development of planned actions to minimise and manage those risks.
- Ensure that the plan is implemented effectively by responsible and trained staff and to test the plan regularly for accuracy, currency, and suitability.

The POEO Act defines pollution as either 'water pollution', 'air pollution', 'noise pollution' or 'land pollution'. 'Pollution incident' means an incident or set of circumstances during, or as a consequence of, which there is or is likely to be a leak, spill or other escape or deposit of a substance. Notification is required if a pollution incident causes or threatens to cause 'material harm to the environment'. If a pollution incident occurs in the course of an activity so that material harm to the environment (within the meaning of section 147 of the POEO Act) is caused or threatened, the person carrying out the activity must **immediately** implement this plan in relation to the activity required by Part 5.7A of the POEO Act.

The POEO Act requires licensees to:

- implement their PIRMP if, in the course of an activity, a pollution incident occurs that causes or threatens to cause material harm (as defined in Box 1.3)
- notify any 'material harm' pollution incidents, in accordance with the requirements set out in the Act.

A copy of this plan must be kept at the licensed premises, or where the activity takes place in the case of mobile plant licences, and be made available on request by an authorised EPA officer and to any person who is responsible for implementing this plan.

ı	Environment Protection	Licence	(EPL)	aetaiis
ı				
•				

Name of licensee:

AFF Properties No 1 Pty Ltd

(including ABN)

EPL number:

11123

Premises name and address:

Warren Gin

9709 Oxley Highway

PO Box 160

Warren NSW 2824 Phone 02 6883 7306

Company or business contact details

Name: Bill Dawson

Position or title: Gin Manager

Business hours contact number/s: 0427 532 143 After hours contact number/s: 0427 532 143 Email: bdawson@australianfoodandfibre.com.au

Website address:

australianfoodandfibre.com.au

Site based activity:

Agricultural Processing

Pollution incident - person/s responsible

If a pollution incident occurs at the site or outside the site because of the site activities, the following individuals have been nominated with key responsibilities.

PIRMP activation

If a material pollution incident occurs this person must immediately implement this PIRMP.

Name: Bill Dawson

Position or title: Gin Manager

Business hours contact number/s: 0427 532 143
After hours contact number/s: 0427 532 143
Email: bdawson@australianfoodandfibre.com.au
Alternative person: Acting shift manager

Pollution incident – person/s responsible, continued				
Notifying relevant authorities	Name: Bill Dawson Position or title: Gin Manager Business hours contact number/s: 0427 532 143 After hours contact number/s: 0427 532 143 Email: bdawson@australianfoodandfibre.com.au Alternative person: Acting shift manager or relative representatives (WHS Manager or Sustainability Manager)			
Managing response to pollution incident	Name: Bill Dawson Position or title: Gin Manager Business hours contact number/s: 0427 532 143 After hours contact number/s: 0427 532 143 Email: bdawson@australianfoodandfibre.com.au			
Managing response to pollution incident – alternate contact person (in absence of responsible person)	Name of person responsible: Wayne Towns Position or title: General Manager - Ginning Business hours contact number/s: 0428 991 480 After hours contact number/s: 0428 991 480 Email: wtowns@australianfoodandfibre.com.au			

Notification of relevant authorities

It is a requirement to **immediately** notify the following regulatory authorities where a pollution incident has or is likely to occur.

Fire and Rescue NSW, the NSW Police and the NSW Ambulance Service are the first responders, as they are responsible for controlling and containing incidents.

Fire and Rescue NSW / Rural Fire Service	Contact number/s:	000
EPA	Contact number/s:	131 555
NSW Health	Relevant Area Health Service: Contact number/s:	Western NSW 02 6809 8600
SafeWork NSW	Contact number/s:	131 055
Local Council	Relevant Area: Contact number/s:	Warren 02 6847 6600
The following individuals and organisations may be needed after a pollution	on incident	
Fire & Rescue NSW (Including Hazardous Materials Response Unit)		000 or 1300 729 579
Ambulance Service of NSW		000 or 131 233 / 02 - 6777 2293
Department of Primary Industries (NSW Fisheries)		1300 550 474
POISONS Information		131 126
NSW Ministry of Health (Public Health Unit)		(Tamworth) 02 - 6764 8000
Department of Families & Community Services		1800 079 098
State Emergency Service (SES)		132 500
Service NSW		13 77 88
Origin Energy		1800 808 526

The POEO Act requires verbal notification to each relevant authority followed by notification in writing within 7 days of the date on which the incident occurred. The initial verbal notification and written notification report must include the following information, if known:

- Time, date and duration of the incident;
- Duration of the event;
- Locations where pollution is occurring or is likely to occur;
- Nature, estimated quantity or volume and concentration of any pollutants involved, if known*;
- Circumstances in which the incident occurred (including the cause of the incident, if known)*; and Action taken or proposed to be taken to deal with the incident and any resulting pollution or threatened pollution

Internal reporting of a pollution incident

In the event of a pollution incident, site personnel must notify the Gin Manager or the acting Shift Manager who will then contact the following personnel:

- General Manager Ginning
- Work, Health & Safety Manager
- Sustainability Manager

Details about the incident and management response will be escalated to the CEO and CFO.

Description and	d likelihood	d of hazards

Site/Facility	Hazard	Likelihood	Pre-emptive actions		
LPG Storage tank	Rupture of tank or fill hose during filling operation.	Low	 Tank is located a reasonable distance from the main gin building and office. Tank undergoes regular maintenance. Tank is filled and maintained by a reputable LPG supplier. Tank is designed with an auto-shut off system, once the pressure within the tank reaches or exceeds a specified threshold or if a potential hazard such as a leak or rupture occurs, the auto shut-off system will be activated. 		
	Fire resulting from leak and external ignition source.	Low	 Fire hoses and fire extinguishers are provided and maintained at tank. Fire truck is in close proximity to tank and other key infrastructure. Area surrounding tank is maintained be free of vegetation and ignition sources. Drainage channels are maintained to minimise weeds. 		
Trash Yard	Fire resulting from burning trash from gin. Fire could be transported and dumped into the trash yard from the Gin Mote, setting alight stored trash.	Low	 Cotton trash remains on site and is processed into mulch/compost via organic breakdown. Trash is stored in windrows which limits the quantity of trash that would burn. The trash yard is isolated from the main work area and module storage yards. Windrows to be kept at distance from each other to eliminate cross fire risk. 		
	Contaminated runoff from yard after rain.	Low	Drainage ditches have been developed to manage the flow of potential run off in a high rainfall or flooding event, which diverts run off water from the trash yard. All runoff is captured in a closed drainage system which runs to a lift pump where it is pumped into earthen wall dam.		
Module Yard	Fire resulting from stored cotton modules could be set on fire through a number of avenues: A "hot" module that is delivered to the yard and ignites.	Low	 The Company has a comprehensive firefighting manual and procedures. AFF has an extensive investment in firefighting equipment. The module yard is separated from the main work areas and a fire would generate a reasonable amount of smoke but would not put people in danger. Any module that is suspect to being "hot" is to be isolated in designated area. 		
	External ignition source.				
Bale Pad	Fire – Stored cotton bales	Low	Staff are trained on identifying at risk bales and on the procedures to manage		

	ignited by fire bales from gin. A fire would generate considerable heat and smoke.		 products which may be subject to fire. Identified fire bales are segregated from the stored bales for a period of fourteen days. Comprehensive firefighting manual and procedures. Extensive investment in firefighting equipment. Fire truck is located in close proximity to the bale pad.
Diesel Fuel Storage	Spill. Tank overfilled, hit by passing machinery	Low	Above ground storage. Not located near waterway, equipment available to contain leaking diesel.
Cyclone System	General site dust Potential cyclone malfunction causing gin dust emissions to atmosphere	Low	 Dust is visually monitored by operations team. If required, water trucks can be used for dust control. Cyclones are located externally to the work area and pose minimal health risk.
Transformer Yard	Fire – Release of inert oil of up to 1000lt from transformers.	Low	 The transformers are owned and maintained by a third-party provider and undergo an inspection and maintenance program. Transformer yards located in areas away from main work areas.
	Toxic fumes and smoke released to atmosphere.	Medium	 Exposure to fumes and smoke could cause serious health problems. Essential Energy will be contacted immediately upon identification of any potential risk of fumes and/or smoke being released.

Inventory of pollutants

The following list outlines the pollutants stored or held on the premises:

Pollutant	Location(s)	
LPG	LPG Storage Tank	
Cotton Trash	Trash Yard	
Gin Dust	Cyclone Rack	
Diesel Fuel	Diesel Storage Shed	
Oil/Toxic Fumes	Electricity Transformer	
Chemical	Electricity Transformer	

Safety equipment

The following list outlines the specified safety equipment needed for specific types of hazards.

Hazard	Equipment	
Fire	Isuzu Fire Truck – On Eastern side of Main Gin Building.	
	Water Tanker – On Eastern side of the trash bin area.	
	Suppressant Foam – On Eastern side of Bale Storage shed. At Airstrip and Yard Storage Shed.	
	Diesel water pump set – Withing fire pump shed	
	Hydrant and hose reel system – Multiple reel and hydrant stations within the gin & bale and seed storage sheds	
	Fire extinguisher – Multiple within the gin and gin buildings.	
Chemical spill	Spill containment kits – located beside all oil storage units and Diesel tanks.	


Communicating with neighbours and the local community

The Gin Manager and the ginning operations team must assess if neighbours or surrounding community members have potentially been affected by a material pollution incident. If this is the case, then community members must be notified without delay by one of the following methods.

- door knocking by a Warren Ginning representative.
- phone call by a Warren Ginning representative; or
- in writing if appropriate for a continuing material pollution incident.

The appropriate method of communication will be determined by the nature of the pollution incident and the communication strategy will be determined by the Gin Manager on a case-by-case basis or as directed by the relevant agency.

A. Key locations



Maps

B. Water storage and run off drainage



Staff training

Training is provided to reduce the potential risks of a pollution incident. All staff are required to attend a seasonal induction and training session at the beginning of each Ginning Season. The induction program will include an information and training session on:

- · Firefighting procedures,
- Module, Trash Yard and Bale Pad surveillance
- Operate Fire Fighting Equipment
- Fire Drills
- Emergency response procedures.

Management staff are required to attend annual crisis management simulation exercise.

Testing and updating of the PIRMP

It is a legal requirement to test the plan every 12 months and within one month of any pollution incident that caused or threatened material harm to the environment.

Date	Pollution Response Scenario		
28/06/2021	Front End Loader on fire in module yard		
25/09/2022	Moon buggy collision with diesel storage tank		
17/10/2023	Fire in trash yard with strong winds blowing towards module yard		
25/10/2024	Electricity Supply Transformer Oil Leak		

This PIRMP has undergone a significant update in 2024 as part of a general review of EPLs and alignment to the EPA guidelines. While annual reviews and updates have been performed historically, this is the first review documented as part of this new process and format.

Review date	Prepared by	Approved by	Nature of review / amendment
10 th October	Kiri Rogan (Sustainability Manager)	Wayne Towns – General	General review of PIRMP and alignment to the EPA
2024	and Craig Gaston (Regional Manager	Manager, Ginning	guidelines.
	- Southern Gins)		

Actions to be taken during or immediately after a pollution incident

Asses

- Identify the risk or potential risk taking into account:
 - · What is the substance being discharged?
 - What is the volume of discharge?
 - · What is the risk to health and safety?
- · Assess the potential for off-site impacts to the community and the environment;
- Ensure the safety of all persons on the site, evacuate if required;
- Call 000 if the incident presents an immediate threat to the health or safety of persons or poses a significant threat to an asset;
- If the discharge cannot be identified evacuate the area and notify relevant stakeholders:
- If the discharge has the potential to cause adverse harm to persons, property or the environment, progress to containment.

Contain

Only proceed to this step if it is safe to do so

- If safe to do so confine the source of the discharge to limit the spread of its effect without endangering personnel;
- Utilise barriers (e.g. absorbent booms, absorbent, banks of soil) to prevent the discharge from spreading; or
- Divert the flow and/or excavate temporary retention dams to withhold the discharge;

Notify

- Call 000 if applicable, then notify the relevant authorities in the following order.
 - 1.Environmental Protection Authority (EPA);
 - 2.NSW Health via the local Public Health Unit;
 - 3.SafeWork NSW:
 - 4.Community members via the Community Notification Protocol (only if required).

Clean up

Only proceed to this step if it is safe to do so

- Clean up and remedial actions to restore the environment are to be in accordance with EPA regulations; and
- · Disposal of pollutants are to be in accordance with EPA regulations;
- Conduct an impact assessment to determine the extent of damage to facilities and/or
 the environment resulting from the incident, identify repairs or restoration that must
 be initiated to minimise further damage and restore the facility for operational use or
 to rehabilitate the environment

Close out

- Assist external authorities with any investigations (if applicable);
- · Conduct an internal investigation (if applicable):
- Complete internal reporting (if applicable);
- Organise restocking of equipment (if applicable)
- Conduct an incident debriefing to inform employees about any hazards that may still remain on the facility property following the incident and to identify unsafe conditions that may still exist.
- Implement corrective actions to avoid reoccurrence.